AlphaTheta

Firmware for DJM-V10 - Change History

ver. 1.20 (15 Jan, 2026 Update)

[NEW]

- ✓ Support for RMX-IGNITE.

  Note: To enable the DIGITAL SEND/RETURN function, connect the MULTI I/O terminal of the unit to the RMX-IGNITE's USB for MULTI I/O terminal using a USB cable.

ver. 1.16 (14 May, 2025 Update)

[FIXED]

- ✓ UASP-compatible USB storage devices could not be recognized.

  NOTE: Please use a non-UASP USB storage drive to apply this update.

  UASP-compatible USB storage devices can be used after this update.

ver. 1.14 (October 17, 2024 update)

[FIXED]

- ✓ Minor issues have been fixed.

ver. 1.13 (July 18, 2024 update)

[IMPROVED]

- ✓ Following the Ecodesign Directive (Directive 2009/125/EC) of theEuropean Union, the time needed for the unit to automatically switchoff has been changed to 20 minutes when the Power Managementfunction is turned on.

  Please note:

- The name of the energy-saving function, (previously called AutoStandby or Auto Power-Off, depending on the model), has nowbeen changed to Power Management.
- To learn more about the Power Management function, see thelatest Instruction Manual, which is available online.

ver. 1.12 (15 December, 2022 Update)

[IMPROVED]

- ✓ Potential audio cut-out issue when connecting the DJM-V10 to theCDJ-3000 via PRO DJ LINK network.

ver. 1.11 (18 November, 2021 Update)

[FIXED]

- ✓ Minor issues.

ver. 1.08 (27 April, 2021 Update)

[NEW]

- ✓ Track titles and artist names will be automatically added to DJM- REC recordings when music is played on a CDJ-3000 in the PRO DJLINK network.

  Note: Be sure to update the CDJ-3000 firmware and DJM-REC app to the latest versions.

ver. 1.07 (29 September, 2020 Update)

[FIXED]

- ✓ Incorrect output of MIDI messages when operated in a certain manner.

ver. 1.05 (26 March, 2020 Update)

[FIXED]

- ✓ Minor issues.

ver. 1.04 (4 February, 2020 Update)

[FIXED]

- ✓ Audio would sometimes fail to input to a channel.