Firmware for XDJ-1000 – CHANGE HISTORY

Ver.1.13 (19 October, 2017 Update)
[FIXED]
- ✓ Track playback speed sometimes did not return to the BPM displayed on the screen when Sync is enabled.
- ✓ A popping noise occurred during a LOOP with QUANTIZE and MASTER TEMPO enabled.
- ✓ A HOT CUE started after jumping to the LOOP-IN point when changing a LOOP BEAT LENGTH with QUANTIZE enabled.

Ver.1.12 (3 April, 2017 Update)
[FIXED]
- ✓ Fixed certain issues during playback and track selection.
- ✓ Some issues when using SLIP HOT CUE.
- ✓ Sometimes SEARCH results did not appear when moving cursor during SEARCH.

Ver.1.10 (10 November, 2016 Update)
[NEW]
- ✓ MASTER PLAYER SELECT (AUTO) support (TORAIZ SP-16 PRO DJ LINK feature)
- ✓ Search using multiple words by adding a space in the [SEARCH] category.

[FIXED]
- ✓ When connected via Pro DJ LINK, some features of the CDJ-2000NXS2 or XDJ-1000MK2 were disabled.
- ✓ Playback of an AIFF music file (24bit/48kHz) stopped and tracks could not be loaded to a deck.
- ✓ Digitally distorted white noise occurred when playing certain .WAV files.
- ✓ Serato DJ: a playing track jumped to the start or first cue point in the Control Mode.
- ✓ Active loop activated a very short loop.
- ✓ macOS 10.12 Sierra: XDJ-1000 was sometimes not recognized as an audio device.

Ver.1.05 (20 August, 2015 Update)
- ✓ Fixed an issue where some HDD may not be recognized when connected to a XDJ-1000.
- ✓ Fixed an issue where a noise may be heard when Master Tempo is activated.

Ver.1.04　(17 February, 2015 Update)
- ✓ Fixed a freeze issue when loading a track where a comment is added to a memory cue in rekordbox 3.1.

Ver.1.03　(15 January, 2015 Update)
- ✓ Supporting Serato DJ.