



## Firmware for DJM-TOUR1 – CHANGE HISTORY

### ver. 2.10 (30 September, 2021 Update)

#### [FIXED]

- ✓ Waveforms from the CDJ-3000 didn't show on the tilt display.  
Note: Update the CDJ-3000 firmware to the latest version.

### ver. 2.09 (14 January, 2020 Update)

#### [FIXED]

- ✓ When used with DJM-REC, sometimes recording or live streaming stopped.

### ver. 2.08 (27 November, 2018 Update)

#### [IMPROVED]

- ✓ Enhanced keyboard operability on the 13-inch fold-out touch screen display.

### ver. 2.07 (15 May, 2018 Update)

#### [IMPROVED]

- ✓ Removed a caution message on the tiltable display when connected via PRO DJ LINK with non-compatible TOUR SYSTEM products.

### ver. 2.06 (19 December, 2017 Update)

#### [FIXED]

- ✓ Incorrect audio input/output signal was sent when connecting to an iOS device.
- ✓ When connecting to an iOS device, connections with the iOS device and the effect channel selector switch did not work.
- ✓ Caution appeared repeatedly on the tiltable display when connecting to DJ players not compatible with the TOURSYSTEM DJ units.

### ver. 2.03 (12 October, 2017 Update)

#### [NEW]

- ✓ Support for TC Supply ShowKontrol software.

### ver. 2.02 (8 August, 2017 Update)

#### [IMPROVED]

- ✓ Cut lag length improved for a more responsive scratch performance.

**[FIXED]**

- ✓ Popping noise occurred via USB audio (FX SEND/RETURN) when switching FX assign on rekordbox with BEAT FX enabled.
- ✓ Fixed other minor issues.

**ver. 2.01 (14 February, 2017 Update)**

**[IMPROVED]**

- ✓ Visibility of RMS meter in WAVEFORM VERTICAL screen.

**[FIXED]**

- ✓ More precise cut lag value on both edges of the crossfader.
- ✓ PRO DJ LINK: The CDJ display froze when connecting to another computer while controlling DJ software from the CDJ using HID control.
- ✓ Small popping noise occurred when turning the EQ/ISO knob when ISOLATOR was selected for EQ CURVE.

**ver. 2.00 (25 October, 2016 Update)**

**[IMPROVED]**

- ✓ Sound quality enhanced by improving internal digital signal dithering process (DSP).
- ✓ AUTO, TAP and BEAT found on the main display visually improved

**[FIXED]**

- ✓ Incorrect audio output when changing Beat FX or FX channels.
- ✓ Channel level indicator was lit when launching.
- ✓ Switching noise occurred when changing USB Output Level.

**ver. 1.10 (2 August, 2016 Update)**

**[NEW]**

- ✓ KUVO real-time information distribution is available when tracks are played on rekordbox dj (Ver.4.2.1).
- ✓ Pioneer DJ logo illumination on the back of the title display can be turned on and off in the Utility setting.

**[FIXED]**

- ✓ Clicking noise occurred when using FILTER of SOUND COLOR FX.
- ✓ Improved stability and fixed minor issues.

**[IMPROVED]**

✓ Response of SOUND COLOR FX buttons and faders.

