



DJM-750MK2 firmware – change history

ver. 1.07 (Jun 23, 2026 update)

[FIXED]

- ✓ Fixed an issue related to audio communication with iOS/iPadOS devices.

ver. 1.06 (July 18, 2024 update)

[IMPROVED]

- ✓ Following the Ecodesign Directive (Directive 2009/125/EC) of the European Union, the time needed for the unit to automatically switch off has been changed to 20 minutes when the Power Management function is turned on.

Please note:

- The name of the energy-saving function, (previously called Auto Standby or Auto Power-Off, depending on the model), has now been changed to Power Management.
- To learn more about the Power Management function, see the latest Instruction Manual, which is available online.

ver. 1.05 (May 18, 2021 update)

[FIXED]

- ✓ Minor issues.

ver. 1.04 (January 15, 2020 update)

[FIXED]

- ✓ When used with DJM-REC, sometimes recording or live streaming stopped.

ver. 1.03 (August 8, 2017 update)

[FIXED]

- ✓ Popping noise occurred via USB audio (FX SEND/RETURN) when switching FX assign on rekordbox with BEAT FX enabled.